

RFQ-Ready Carbide Buyer Checklist

What to include so carbide quote review starts cleanly

1

Drawing or sketch

Finished geometry, critical dimensions, datums, and tolerance callouts.

2

Grade or application

Known carbide grade or the wear mode: abrasion, impact, corrosion, heat, or galling.

3

Quantity and schedule

Prototype, production, annual volume, target delivery, and release cadence.

4

Starting form

Rod, blank, stock shape, near-net blank, or finished component requirement.

5

Finish and allowance

Ground, as-sintered, polished, EDM, lapped, oversize stock, or grind allowance.

6

Inspection needs

Material certs, traceability, inspection reports, packaging, or quality documentation.

Fastest next step

Send drawings, grade needs, quantity, finish requirements, and application notes through the Extramet RFQ form.